







$\varnothing d$	$l$		$\varnothing d_m$		
(mm)	(mm)	(mm)	(mm)	(N)	(N)
4,8	11,5	3,5-6,0	$\approx 3,02$	3600	3920/6270
4,8	14,0	6,0-8,5	$\approx 3,02$	3600	3920/6270
6,4	10,5	2,8-4,8	$\approx 4,17$	6600	5390/11180
6,4	12,5	4,8-6,8	$\approx 4,17$	6600	5390/11180

$\varnothing d$	$l$		$\varnothing d_m$		
(mm)	(mm)	(mm)	(mm)	(N)	(N)
6,4	14,5	6,8-8,8	$\approx 4,17$	6600	5390/11180
6,4	16,5	8,8-10,8	$\approx 4,17$	6600	5390/11180
6,4	18,5	10,8-12,8	$\approx 4,17$	6600	5390/11180
6,4	20,5	12,8-14,8	$\approx 4,17$	6600	5390/11180