







$\emptyset d$	l		$\emptyset d_m$		
(mm)	(mm)	(mm)	(mm)	(N)	(N)
4,0	8,0	2,0-4,0	$\approx 2,50$	3800	3100
4,0	10,0	4,0-6,0	$\approx 2,50$	3800	3100
4,0	12,0	6,0-8,0	$\approx 2,50$	3800	3100
4,0	15,0	9,0-11,0	$\approx 2,50$	3800	3100

$\emptyset d$	l		$\emptyset d_m$		
(mm)	(mm)	(mm)	(mm)	(N)	(N)
4,8	8,0	1,5-3,0	$\approx 2,90$	6000	4500
4,8	10,0	3,0-5,0	$\approx 2,90$	6000	4500
4,8	12,0	5,0-7,0	$\approx 2,90$	6000	4500
4,8	15,0	8,0-10,0	$\approx 2,90$	6000	4500