







$\varnothing d$	$l$		$\varnothing d_m$		
(mm)	(mm)	(mm)	(mm)	(N)	(N)
4,0	6,0	0,5-1,5	$\approx 2,30$	2500	2300
4,0	8,0	1,5-3,0	$\approx 2,30$	2500	2300
4,0	12,0	5,0-6,5	$\approx 2,30$	2500	2300
4,0	15,0	6,5-10,5	$\approx 2,30$	2500	2300

$\varnothing d$	$l$		$\varnothing d_m$		
(mm)	(mm)	(mm)	(mm)	(N)	(N)
4,8	8,0	1,0-3,0	$\approx 2,90$	3800	2900
4,8	12,0	5,0-6,5	$\approx 2,90$	3800	2900
4,8	16,0	6,5-10,5	$\approx 2,90$	3800	2900