


$\varnothing d$	l	mm	$\varnothing d_m$	mm	N	N
3,2	11,4	1,6-6,4	$\approx 2,05$	1400	1100	
4,0	12	1,6-6,4	$\approx 2,65$	2100	1800	
4,0	13,6	3,2-8,0	$\approx 2,65$	2100	1800	



$\varnothing d$	l	mm	$\varnothing d_m$	mm	N	N
4,8	12,7	1,6-6,4	$\approx 3,00$	3100	2600	
4,8	14,3	3,2-8,0	$\approx 3,00$	3100	2600	
4,8	19,3	8,0-12,7	$\approx 3,00$	3100	2600	