







$\varnothing d$	l		$\varnothing d_m$		
(mm)	(mm)	(mm)	(mm)	(N)	(N)
3,2	7,5	1,5-3,5	$\approx 1,70$	1245	1070
3,2	9,0	3,0-5,0	$\approx 1,70$	1245	1070
3,2	10,5	4,5-6,5	$\approx 1,70$	1245	1070
3,2	12,0	6,0-7,5	$\approx 1,70$	1245	1070
4,0	9,5	3,0-5,0	$\approx 2,20$	2240	1710
4,0	11,0	4,5-6,5	$\approx 2,20$	2240	1710
4,0	12,5	6,0-8,0	$\approx 2,20$	2240	1710

$\varnothing d$	l		$\varnothing d_m$		
(mm)	(mm)	(mm)	(mm)	(N)	(N)
4,8	9,5	2,5-4,5	$\approx 2,65$	3070	2230
4,8	11,0	4,0-6,0	$\approx 2,65$	3070	2230
4,8	12,5	5,5-7,5	$\approx 2,65$	3070	2230
4,8	14,0	7,0-9,0	$\approx 2,65$	3070	2230
4,8	15,5	8,5-10,5	$\approx 2,65$	3070	2230
4,8	19,0	12,0-14,0	$\approx 2,65$	3070	2230