







$\varnothing d$	l		$\varnothing d_m$		
(mm)	(mm)	(mm)	(mm)	(N)	(N)
3,2	6,0	0,5-1,5	$\approx 1,90$	2500	2000
3,2	8,0	1,5-3,0	$\approx 1,90$	2500	2000
3,2	9,5	3,0-5,0	$\approx 1,90$	2500	2000
3,2	12,0	5,0-7,0	$\approx 1,90$	2500	2000
4,0	6,0	0,5-1,5	$\approx 2,30$	4000	3000
4,0	8,0	1,5-3,0	$\approx 2,30$	4000	3000
4,0	9,5	3,0-5,0	$\approx 2,30$	4000	3000

$\varnothing d$	l		$\varnothing d_m$		
(mm)	(mm)	(mm)	(mm)	(N)	(N)
4,0	12,0	5,0-6,5	$\approx 2,30$	4000	3000
4,0	16,0	6,5-10,5	$\approx 2,30$	4000	3000
4,8	8,0	1,0-3,0	$\approx 2,90$	5500	4500
4,8	9,5	3,0-5,0	$\approx 2,90$	5500	4500
4,8	12,0	5,0-6,5	$\approx 2,90$	5500	4500
4,8	16,0	6,5-10,5	$\approx 2,90$	5500	4500