







$\varnothing d$	l		$\varnothing d_m$		
mm	mm	mm	mm	N	N
3,2	6,6	1,0-3,0	$\approx 2,10$	2000	1600
3,2	9,2	3,0-5,0	$\approx 2,10$	2000	1700
3,2	11,5	5,0-7,0	$\approx 2,10$	2000	2500
4,0	7,5	1,0-3,0	$\approx 2,60$	4000	4200
4,0	9,5	3,0-5,0	$\approx 2,60$	4000	4200

$\varnothing d$	l		$\varnothing d_m$		
mm	mm	mm	mm	N	N
4,0	12,5	5,0-7,0	$\approx 2,60$	4000	4200
4,8	10	1,5-3,5	$\approx 3,20$	5000	5500
4,8	12	3,5-6,0	$\approx 3,20$	5000	5500
4,8	14,3	6,0-8,5	$\approx 3,20$	5000	5500