


$\varnothing d$	l	mm	$\varnothing d_m$	mm	N	N
3,2	9,9	1,0-4,8	$\approx 2,20$	2000	1700	
4,0	12	1,6-6,4	$\approx 2,70$	3200	2900	
4,0	13,6	3,2-8,0	$\approx 2,70$	3200	2900	
4,0	16,8	6,4-11,2	$\approx 2,70$	3200	2900	



$\varnothing d$	l	mm	$\varnothing d_m$	mm	N	N
4,8	12,7	1,6-6,4	$\approx 3,10$	4800	4100	
4,8	14,3	3,2-8,0	$\approx 3,10$	4800	4100	
4,8	17,5	6,4-11,2	$\approx 3,10$	4800	4100	
4,8	19,3	8,0-12,7	$\approx 3,10$	4800	4100	