


$\varnothing d$	I	$\varnothing d_m$	$\varnothing d_m$	N	N
mm	mm	mm	mm	N	N
4,0	6	0,5-1,5	$\approx 2,30$	2500	2300
4,0	8	1,5-3,0	$\approx 2,30$	2500	2300
4,0	12	5,0-6,5	$\approx 2,30$	2500	2300
4,0	15	6,5-10,5	$\approx 2,30$	2500	2300



$\varnothing d$	I	$\varnothing d_m$	$\varnothing d_m$	N	N
mm	mm	mm	mm	N	N
4,8	8	1,0-3,0	$\approx 2,90$	3800	2900
4,8	12	5,0-6,5	$\approx 2,90$	3800	2900
4,8	16	6,5-10,5	$\approx 2,90$	3800	2900