







$\varnothing d$	l		$\varnothing d_m$		
mm	mm	mm	mm	N	N
3,0	6	1,5-2,5	≈ 1,90	2000	1600
3,0	8	2,5-4,5	≈ 1,90	2000	1600
3,0	10	4,5-6,5	≈ 1,90	2000	1600
3,0	12	6,5-8,5	≈ 1,90	2000	1600
3,0	15	9,5-11,5	≈ 1,90	2000	1600
3,2	6	1,5-2,5	≈ 2,00	2500	1800
3,2	8	2,5-4,5	≈ 2,00	2500	1800
3,2	10	4,5-6,5	≈ 2,00	2500	1800
3,2	12	6,5-8,5	≈ 2,00	2500	1800
3,2	15	8,5-12,0	≈ 2,00	2500	1800
4,0	6	≈ 2,0	≈ 2,50	3800	3100
4,0	8	2,0-4,0	≈ 2,50	3800	3100
4,0	10	4,0-6,0	≈ 2,50	3800	3100
4,0	13	7,0-9,0	≈ 2,50	3800	3100
4,0	14	9,0-10,0	≈ 2,50	3800	3100
4,0	16	10,0-12,0	≈ 2,50	3800	3100
4,0	18	12,0-14,0	≈ 2,50	3800	3100
4,0	20	14,0-16,0	≈ 2,50	3800	3100

$\varnothing d$	l		$\varnothing d_m$		
mm	mm	mm	mm	N	N
4,0	25	17,0-21,0	≈ 2,50	3800	3100
4,8	8	1,5-3,0	≈ 2,90	6000	4500
4,8	10	3,0-5,0	≈ 2,90	6000	4500
4,8	12	5,0-7,0	≈ 2,90	6000	4500
4,8	16	9,0-11,0	≈ 2,90	6000	4500
4,8	18	11,0-13,0	≈ 2,90	6000	4500
4,8	20	13,0-15,0	≈ 2,90	6000	4500
4,8	25	15,0-20,0	≈ 2,90	6000	4500
4,8	27	18,0-22,0	≈ 2,90	6000	4500
4,8	30	20,0-25,0	≈ 2,90	6000	4500
5,0	8	1,5-3,0	≈ 2,90	6500	5000
5,0	10	3,0-5,0	≈ 2,90	6500	5000
5,0	12	5,0-7,0	≈ 2,90	6500	5000
5,0	16	9,0-11,0	≈ 2,90	6500	5000
5,0	18	11,0-13,0	≈ 2,90	6500	5000
5,0	20	13,0-15,0	≈ 2,90	6500	5000
5,0	25	17,0-20,0	≈ 2,90	6500	5000