


$\varnothing d$	l	$\varnothing d_m$	$\varnothing d_m$	N	N
mm	mm	mm	mm	N	N
4,0	8	2,0-4,0	$\approx 2,50$	3800	3100
4,0	10	4,0-6,0	$\approx 2,50$	3800	3100
4,0	12	6,0-8,0	$\approx 2,50$	3800	3100
4,0	15	9,0-11,0	$\approx 2,50$	3800	3100



$\varnothing d$	l	$\varnothing d_m$	$\varnothing d_m$	N	N
mm	mm	mm	mm	N	N
4,8	8	1,5-3,0	$\approx 2,90$	6000	4500
4,8	10	3,0-5,0	$\approx 2,90$	6000	4500
4,8	12	5,0-7,0	$\approx 2,90$	6000	4500
4,8	15	8,0-10,0	$\approx 2,90$	6000	4500