







$\varnothing d$	$l$		$\varnothing d_m$		
(mm)	(mm)	(mm)	(mm)	(N)	(N)
3,0	6,0	1,0-3,0	$\approx 1,75$	700	600
3,0	8,0	3,0-5,0	$\approx 1,75$	700	600
3,0	10,0	5,0-7,0	$\approx 1,75$	700	600
3,0	12,0	7,0-9,0	$\approx 1,75$	700	600
4,0	6,0	1,0-2,5	$\approx 2,10$	1500	1000

$\varnothing d$	$l$		$\varnothing d_m$		
(mm)	(mm)	(mm)	(mm)	(N)	(N)
4,0	8,0	2,5-4,5	$\approx 2,10$	1500	1000
4,0	10,0	4,5-6,5	$\approx 2,10$	1500	1000
4,0	12,0	6,5-8,5	$\approx 2,10$	1500	1000
4,0	16,0	10,5-12,5	$\approx 2,10$	1500	1000