


$\varnothing d$	l	$\varnothing d_m$	N	N (min/max)	
mm	mm	mm	mm	N (min/max)	
4,8	11,5	3,5-6,0	$\approx 3,02$	3600	3920/6270
4,8	14	6,0-8,5	$\approx 3,02$	3600	3920/6270
6,4	10,5	2,8-4,8	$\approx 4,17$	6600	5390/11180
6,4	12,5	4,8-6,8	$\approx 4,17$	6600	5390/11180



$\varnothing d$	l	$\varnothing d_m$	N	N (min/max)	
mm	mm	mm	mm	N (min/max)	
6,4	14,5	6,8-8,8	$\approx 4,17$	6600	5390/11180
6,4	16,5	8,8-10,8	$\approx 4,17$	6600	5390/11180
6,4	18,5	10,8-12,8	$\approx 4,17$	6600	5390/11180
6,4	20,5	12,8-14,8	$\approx 4,17$	6600	5390/11180